

Technical Bulletin

Preparing Bill Acceptor to accept

2014 New Series Polymer Banknotes


Date: 2013/11/16

International Currency Technologies Corp.

Technical Bulletin 2014 New Canadian Polymer Notes	Approved: Richard Yang	Prepared by: Terry Huang Version: ICTA 131116
Purpose:		
Due to the new designed of the r acceptors in the field will	new Canadian polymer ban need to complete the sense	•
Following instructions will give of calibration procedures, wi amendments.	detail information about the hich is required within rece	
Firmware Version: TS5FJCAA4	(8806)	
Support Banknotes: 5(02,06,1		12)

International Currency Technologies Corp.

Make the connection as following figure:




Procedures:

Step1. Use PC download tool to save the latest firmware into FP-004; turn the power on and make sure the programmer's LED is flashing.



International Currency Technologies Corp.

Step2. Press and hold button of FP-004 until the download process begin.



Step3. Download finished, make sure FP-004 LED keeps flashing a green light.




Step4. Press the side button once again to enter the calibration mode.

(If you are using the FP001 will be the same procedure, the only difference is when you see the orange LED on the status location)

Step5. Than insert sensor calibration card to make sensor adjustment.



Calibration Direction:



Attention:

- 1. Please follow the arrow direction to insert the calibration cards.
- 2. Make sure the bill acceptor two times in and out during the calibration process.
- 3. If you do not have the calibration card, please contact ICT America for assistant.

Contact Information:

International Currency Technologies Corporation (HQ) No 24, Alley 38, Lane 91, Neihu Rd., Sec. 1, Taipei City 114, Taiwan, R.O.C. Tel: 886-2-2797-1238 Fax:886-2-2797-1634 E-mail: <u>rma@ictgroup.com.tw</u>

ICT USA Address: 48929 Milmont Dr., Fremont, CA 94538, USA Tel: +1-510-353-0289 Fax: +1-510-353-0399 E-mail: <u>sales@ict-america.com</u>